

July 23, 2013

Mr. Ed Rawski, P.E.  
Pennsylvania Department of Environmental Protection  
Bureau of Waste Management  
909 Elmerton Avenue  
Harrisburg, PA 17110-8200

RE: Frey Farm Landfill; Landfill Gas Monitoring; BWM Permit #101389  
2<sup>nd</sup> Quarter 2013 Perimeter %LEL LFG Report


Dear Mr. Rawski:

In accordance with the Municipal Waste Management Regulations (§273.292 – “Gas Control and Monitoring”), the Lancaster County Solid Waste Management Authority (LCSWMA) continues quarterly monitoring of methane gas levels at the perimeter of the above referenced facility.

LCSWMA personnel completed monitoring of sample points along the facility boundary and in adjacent buildings and structures on June 24, 2013. The results of that monitoring are attached. No sampled peripheral locations, structures or landfill gas monitoring probes were found to contain landfill gases while two (2) manholes, internal to the landfill, were found to contain methane.

We will continue to submit the results from this ongoing quarterly monitoring program. Please feel free to contact me if you have any questions or require additional information in any regard.

Sincerely,



Brooks K. Norris  
Senior Manager, Technical Services

Attachment

cc: Bob Zorbaugh  
Randy Weiss (PADEP)  
cc/att: Jeff Musser  
Bob Eshbach  
Emily West  
Anthony Lutkus (PaDEP)

[www.lcswma.org](http://www.lcswma.org)

1299 HARRISBURG PIKE | PO BOX 4425 | LANCASTER, PA 17604  
PHONE: 717-397-9968 FAX: 717-397-9973

FREY FARM LANDFILL METHANE MONITORING PROGRAM  
SAMPLE POINT INSPECTION FORM

SAMPLE POINT NUMBER	DESCRIPTION	DATE	DATE
1	PUMP STATION; AIR SPACE	0	0
2	PUMP STATION; STRUCTURE INTERIOR	0	0
3	MANHOLE 1S	0	22
4,5,6,7	(DELETED)		No Longer Monitored
8	SEE MAP	0	0
9	SEE MAP	0	0
10	SEE MAP	0	0
11	SEE MAP	0	0
12	SEE MAP	0	0
13	SEE MAP	0	0
14	SEE MAP	0	0
15	SEE MAP	0	0
16	SEE MAP	0	0
17	SEE MAP	0	0
18	FFLTP; INFLUENT PIPE GALLEY	0	0
19	MANHOLE 2PB	15	3
20	MANHOLE 2IA-P	0	0
21	MANHOLE 2IB-P	0	0
22	NW CELL 2 (SEE MAP)	0	0
23	SEE MAP	0	0
24	SEE MAP	0	0
25	MANHOLE 3A-S	0	0
26	MANHOLE 3A-P	0	0
27	FFMP005W	0	0
28	FFMP013W	0	0
29	FFMP016W	0	0
30	TRUCKWASH DRAIN PIT	0	0
31	MAINTENANCE BUILDING OFFICE	0	0
32	MAINTENANCE BUILDING LUNCH ROOM	0	0
33	MAINTENANCE BUILDING STORAGE AREA	0	0
34	COMPLIANCE BUILDING LAB	0	0
35	COMPLIANCE BUILDING OFFICE	0	0
36	FFLTP EQ. TANKS METER PIT	0	0
37	CELL 1 CLEANOUT		No Longer Monitored
38	LASA PUMP STATION STRUCTURE INTERIOR	0	0
39	LASA PUMP STATION AIR SPACE	0	0
40	MANHOLE 4S	0	0

Revised Date: Feb '11 - Added LFG Probe locations 49 through 56

FREY FARM LANDFILL METHANE MONITORING PROGRAM  
SAMPLE POINT INSPECTION FORM

SAMPLE NO.	DESCRIPTION	DATE	DATE
41	MANHOLE 4P	0	0
42	MANHOLE 5S	0	0
43	MANHOLE 5P	0	0
44	MANHOLE 5SW	0	0
45	MANHOLE 5PB	0	0
-----			
46	MANHOLE 6S	0	0
47	MANHOLE 6P	0	0
48	MANHOLE 6-FM	0	0
49	FFGMP001	0	0
50	FFGMP002	0	0
-----			
51	FFGMP003	0	0
52	FFGMP004	0	0
53	FFGMP005	0	0
54	FFGMP006	0	0
55	FFGMP007	0	0
-----			
56	FFGMP008	0	0
	Atmospheric Pressure	29.33"	29.55"
	Air Temperature (Deg. C)	6.9 °C	28.1 °C

Revised Date: Feb '11 - Added LFG Probe locations 49 through