

1299 HARRISBURG PIKE | PO BOX 4425 | LANCASTER, PA 17604 PHONE: 717-397-9968 | FAX: 717-397-9973

www.lcswma.org

April 16, 2020

Mr. Ed Rawski, P.E.
Pennsylvania Department of Environmental Protection
Bureau of Waste Management
909 Elmerton Avenue
Harrisburg, PA 17110-8200

RE: Creswell Landfill; Landfill Gas Monitoring; BWM Permit #10008

1st Quarter 2020 Perimeter %LEL LFG Report

Dear Mr. Rawski:

In accordance with the Municipal Waste Management Regulations (§273.292 – "Gas Control and Monitoring"), the Lancaster County Solid Waste Management Authority (LCSWMA) continues quarterly monitoring of methane gas levels at the perimeter of the above referenced facility.

LCSWMA personnel completed monitoring of sample points along the facility boundary and in adjacent buildings and structures March 30, 2020. The results of that monitoring are attached. No sampled peripheral locations, structures, landfill gas monitoring probes or manholes (sampled on 3/30/20) were found to contain methane.

Please do not hesitate in contacting me at dbrown@lcswma.org, if you have any questions or concerns.

Respectfully Submitted,

Daniel A. Brown

**Environmental Compliance Manager** 

Cc: LCSWMA Environmental

Daniel a. Brown

PA DEP: Randy Weiss

## CRESWELL METHANE MONITORING PROGRAM SAMPLE POINT INSPECTION FORM

SAMPLE		METHANE LEVEL (as % LEL)				
POINT	DESCRIPTION	DATE	DATE	DATE	DATE	
NUMBER		3/30/20				
1 to 15	GP WELLS	not included with this monitoring				
16	CONTROL BUILDING LAB	0				
17	CONTROL BUILDING COMPRESSOR ROOM	0				
18	CONTROL BUILDING LOCKER ROOM	0				
19	NTHW PIT	no longer exists				
20	OTHW PIT	0				
21	LTS AERATION PIT AT WEATHER STATION #1	0				
22	LTS AERATION PIT AT WEATHER STATION #2	0				
23	LTS WIRE TRENCH VENTS 1	0				
24	LTS WIRE TRENCH VENTS 2	0				
25	LTS WIRE TRENCH VENTS 3	no longer exists				
26	PUMP HOUSE	0				
27	PUMP HOUSE WET WELL	0				
28	MH #1	0				
29	MH #2	0				
30	INLET; STREAM R PIPE	0				
31	OUTLET; STREAM R PIPE	0				
32	UPPER END; RAVINE LEACHATE COLLECTION C.O.	no longer exists				
33	SEE MAP	0				
34	SEE MAP	0				
35	SEE MAP	0				
36	SEE MAP	0				
37	SEE MAP	0				
38	SEE MAP	0				
39	SEE MAP	0				
40	SEE MAP	0				
41	SEE MAP	0				
42	SEE MAP	0				
43	SEE MAP	0				
44	SEE MAP	0				
45	SEE MAP	0				
46	SEE MAP	0				
47	SEE MAP	0				
48	SEE MAP	0				
49	SEE MAP	0				
50	SEE MAP	0				
	Atmospheric Pressure (in. Hg)	30.08"				
	Air Temperature (Deg. C)	3.72°C				

Revision Date: June 2011

Revisions: deleted points 62 to 66; added points 81 through 86

## CRESWELL METHANE MONITORING PROGRAM SAMPLE POINT INSPECTION FORM

SAMPLE		N	METHANE LEVEL (as % LEL)				
POINT	DESCRIPTION	DATE	DATE	DATE	DATE		
NUMBER		3/30/20					
51	LTS DISCHARGE MH #1	0					
52	LTS DISCHARGE MH #2	0					
53	DRAIN PIPE UNDER RAVINE PHASE II	0					
54	OLD SCALE HOUSE PIT	no longer monitored					
55	NEW SCALE HOUSE PIT	no longer exists					
56	LAGOON LINER BALLOON 1	NA	NA	NA	NA		
57	LEACHATE PIPE LOWER END OF RAVINE	capped; no longer monitored					
58	CWOB092W	0					
59	CWOB093A	0					
60	CWOB093B (aka CWMP016W)	0					
61	CWOB080W (formerly CWMP006W)	0					
62	CWGMP002; Gas monitoring probe						
63	CWGMP04A; Gas monitoring probe						
64	CWGMP04B; Gas monitoring probe	abandor	ned for Soil Bo	orrow Project	stockpile		
65	CWGMP06A; Gas monitoring probe						
66	CWGMP06B; Gas monitoring probe						
67	CWGMP08A; Gas monitoring probe	0					
68	CWGMP08B; Gas monitoring probe	0					
69	CWGMP08C; Gas monitoring probe	0					
70	CWGMP10A; Gas monitoring probe	0					
71	CWGMP10B; Gas monitoring probe	0					
72	CWGMP10C; Gas monitoring probe	0					
73	CWO100DW	0					
74	CWO100SW	0					
75	CWGMP12A; Gas Monitoring Probe	0					
76	CWGMP12B; Gas Monitoring Probe	0					
77	CWGMP13A; Gas Monitoring Probe	0					
78	CWGMP13B; Gas Monitoring Probe	0					
79	CWGMP14A; Gas Monitoring Probe	0					
80	CWGMP14B; Gas Monitoring Probe	0					
81	CWGMP018; Gas Monitoring Probe	0					
82	CWGMP019; Gas Monitoring Probe	0					
83	CWGMP020; Gas Monitoring Probe	0					
84	CWGMP021; Gas Monitoring Probe	0					
85	CWGMP022; Gas Monitoring Probe	0					
86	CWGMP023; Gas Monitoring Probe	0					

<sup>&</sup>lt;sup>1</sup> Liner was repaired; "NA" indicates point was inspected and balloon has not reoccurred

Revision Date: June 2011

Revisions: deleted points 62 to 66; added points 81 through 86