

CRESWELL METHANE MONITORING PROGRAM
SAMPLE POINT INSPECTION FORM

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 3/19/25	DATE	DATE	DATE
1 to 15	GP WELLS	not included with this monitoring			
16	CONTROL BUILDING LAB	0			
17	CONTROL BUILDING COMPRESSOR ROOM	0			
18	CONTROL BUILDING LOCKER ROOM	0			
19	NTHW PIT	no longer exists			
20	OTHW PIT	0			
21	LTS AERATION PIT AT WEATHER STATION #1	0			
22	LTS AERATION PIT AT WEATHER STATION #2	0			
23	LTS WIRE TRENCH VENTS 1	0			
24	LTS WIRE TRENCH VENTS 2	0			
25	LTS WIRE TRENCH VENTS 3	no longer exists			
26	PUMP HOUSE	0			
27	PUMP HOUSE WET WELL	0			
28	MH #1	0			
29	MH #2	0			
30	INLET; STREAM R PIPE	0			
31	OUTLET; STREAM R PIPE	0			
32	UPPER END; RAVINE LEACHATE COLLECTION C.O.	no longer exists			
33	SEE MAP	0			
34	SEE MAP	0			
35	SEE MAP	0			
36	SEE MAP	0			
37	SEE MAP	0			
38	SEE MAP	0			
39	SEE MAP	0			
40	SEE MAP	0			
41	SEE MAP	0			
42	SEE MAP	0			
43	SEE MAP	0			
44	SEE MAP	0			
45	SEE MAP	0			
46	SEE MAP	0			
47	SEE MAP	0			
48	SEE MAP	0			
49	SEE MAP	0			
50	SEE MAP	0			
	Atmospheric Pressure (in. Hg)	29.96"			
	Air Temperature (Deg. C)	18.9°C			

Revision Date: June 2011

Revisions: deleted points 62 to 66; added points 81 through 86

page 1 of 2

**CRESWELL METHANE MONITORING PROGRAM
SAMPLE POINT INSPECTION FORM**

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 3/19/25	DATE	DATE	DATE
51	LTS DISCHARGE MH #1	0			
52	LTS DISCHARGE MH #2	0			
53	DRAIN PIPE UNDER RAVINE PHASE II	0			
54	OLD SCALE HOUSE PIT	no longer monitored			
55	NEW SCALE HOUSE PIT	no longer exists			
56	LAGOON LINER BALLOON ¹	NA	NA	NA	NA
57	LEACHATE PIPE LOWER END OF RAVINE	capped; no longer monitored			
58	CWOB092W	0			
59	CWOB093A	0			
60	CWOB093B (aka CWMP016W)	0			
61	CWOB080W (formerly CWMP006W)	0			
62	CWGMP002; Gas monitoring probe	abandoned for Soil Borrow Project stockpile			
63	CWGMP04A; Gas monitoring probe				
64	CWGMP04B; Gas monitoring probe				
65	CWGMP06A; Gas monitoring probe				
66	CWGMP06B; Gas monitoring probe				
67	CWGMP08A; Gas monitoring probe	0			
68	CWGMP08B; Gas monitoring probe	0			
69	CWGMP08C; Gas monitoring probe	0			
70	CWGMP10A; Gas monitoring probe	0			
71	CWGMP10B; Gas monitoring probe	0			
72	CWGMP10C; Gas monitoring probe	0			
73	CWO100DW	0			
74	CWO100SW	0			
75	CWGMP12A; Gas Monitoring Probe	0			
76	CWGMP12B; Gas Monitoring Probe	0			
77	CWGMP13A; Gas Monitoring Probe	0			
78	CWGMP13B; Gas Monitoring Probe	0			
79	CWGMP14A; Gas Monitoring Probe	0			
80	CWGMP14B; Gas Monitoring Probe	0			
81	CWGMP018; Gas Monitoring Probe	0			
82	CWGMP019; Gas Monitoring Probe	0			
83	CWGMP020; Gas Monitoring Probe	0			
84	CWGMP021; Gas Monitoring Probe	0			
85	CWGMP022; Gas Monitoring Probe	0			
86	CWGMP023; Gas Monitoring Probe	0			

¹ Liner was repaired; "NA" indicates point was inspected and balloon has not reoccurred

Revision Date: June 2011

Revisions: deleted points 62 to 66; added points 81 through 86

page 2 of 2