

CRESWELL METHANE MONITORING PROGRAM
SAMPLE POINT INSPECTION FORM

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 3/19/25	DATE 6/30/25	DATE	DATE
1 to 15	GP WELLS	not included with this monitoring			
16	CONTROL BUILDING LAB	0	0		
17	CONTROL BUILDING COMPRESSOR ROOM	0	0		
18	CONTROL BUILDING LOCKER ROOM	0	0		
19	NTHW PIT	no longer exists			
20	OTHW PIT	0	0		
21	LTS AERATION PIT AT WEATHER STATION #1	0	0		
22	LTS AERATION PIT AT WEATHER STATION #2	0	0		
23	LTS WIRE TRENCH VENTS 1	0	0		
24	LTS WIRE TRENCH VENTS 2	0	0		
25	LTS WIRE TRENCH VENTS 3	no longer exists			
26	PUMP HOUSE	0	0		
27	PUMP HOUSE WET WELL	0	0		
28	MH #1	0	0		
29	MH #2	0	0		
30	INLET; STREAM R PIPE	0	0		
31	OUTLET; STREAM R PIPE	0	0		
32	UPPER END; RAVINE LEACHATE COLLECTION C.O.	no longer exists			
33	SEE MAP	0	0		
34	SEE MAP	0	0		
35	SEE MAP	0	0		
36	SEE MAP	0	0		
37	SEE MAP	0	0		
38	SEE MAP	0	0		
39	SEE MAP	0	0		
40	SEE MAP	0	0		
41	SEE MAP	0	0		
42	SEE MAP	0	0		
43	SEE MAP	0	0		
44	SEE MAP	0	0		
45	SEE MAP	0	0		
46	SEE MAP	0	0		
47	SEE MAP	0	0		
48	SEE MAP	0	0		
49	SEE MAP	0	0		
50	SEE MAP	0	0		
	Atmospheric Pressure (in. Hg)	30.04"	30.11"		
	Air Temperature (Deg. C)	26.11°C	32.78°C		

Revision Date: June 2011

Revisions: deleted points 62 to 66; added points 81 through 86

page 1 of 2

**CRESWELL METHANE MONITORING PROGRAM
SAMPLE POINT INSPECTION FORM**

SAMPLE POINT NUMBER	DESCRIPTION	METHANE LEVEL (as % LEL)			
		DATE 3/19/25	DATE 6/30/25	DATE	DATE
51	LTS DISCHARGE MH #1	0	0		
52	LTS DISCHARGE MH #2	0	0		
53	DRAIN PIPE UNDER RAVINE PHASE II	0	0		
54	OLD SCALE HOUSE PIT	no longer monitored			
55	NEW SCALE HOUSE PIT	no longer exists			
56	LAGOON LINER BALLOON ¹	NA	NA	NA	NA
57	LEACHATE PIPE LOWER END OF RAVINE	capped; no longer monitored			
58	CWOB092W	0	0		
59	CWOB093A	0	0		
60	CWOB093B (aka CWMP016W)	0	0		
61	CWOB080W (formerly CWMP006W)	0	0		
62	CWGMP002; Gas monitoring probe	abandoned for Soil Borrow Project stockpile			
63	CWGMP04A; Gas monitoring probe				
64	CWGMP04B; Gas monitoring probe				
65	CWGMP06A; Gas monitoring probe				
66	CWGMP06B; Gas monitoring probe				
67	CWGMP08A; Gas monitoring probe	0	0		
68	CWGMP08B; Gas monitoring probe	0	0		
69	CWGMP08C; Gas monitoring probe	0	0		
70	CWGMP10A; Gas monitoring probe	0	0		
71	CWGMP10B; Gas monitoring probe	0	0		
72	CWGMP10C; Gas monitoring probe	0	0		
73	CWO100DW	0	0		
74	CWO100SW	0	0		
75	CWGMP12A; Gas Monitoring Probe	0	0		
76	CWGMP12B; Gas Monitoring Probe	0	0		
77	CWGMP13A; Gas Monitoring Probe	0	0		
78	CWGMP13B; Gas Monitoring Probe	0	0		
79	CWGMP14A; Gas Monitoring Probe	0	0		
80	CWGMP14B; Gas Monitoring Probe	0	0		
81	CWGMP018; Gas Monitoring Probe	0	0		
82	CWGMP019; Gas Monitoring Probe	0	0		
83	CWGMP020; Gas Monitoring Probe	0	0		
84	CWGMP021; Gas Monitoring Probe	0	0		
85	CWGMP022; Gas Monitoring Probe	0	0		
86	CWGMP023; Gas Monitoring Probe	0	0		

¹ Liner was repaired; "NA" indicates point was inspected and balloon has not reoccurred

Revision Date: June 2011

Revisions: deleted points 62 to 66; added points 81 through 86

page 2 of 2